

	Drucken	ICA	Duplex Drucken	Broschürend ruck	TWAIN/WIA	Scan-to-E-Mail/Bild/T ext/Datei	Scan-to-E-Mail-Server	Scan-to-FTP	Scan-to-SMB	Scan-to-USB-Stick	Scan-to-Speicherka rte	Speicherkarten-Station	USB-Host	PC-Fax Senden	PC-Fax Empfangen	PaperPort	Presto! Page Manager	Face Filter	Control Center	Remote Setup	Brother Status Monitor	Web-based Management	BRAdmin Professional	BRAdmin Light
Windows 8	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X	
Windows 8 x64	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X	
Windows 8 RT	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X								
Windows 2000	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X	
Windows XP	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X	
Windows XP x64 Edition	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X	
Windows Vista	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X	
Windows Vista x64 Edition	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X	
Windows 7	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X	
Windows 7 x64 Edition	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X	
Windows Server 2003	X		X	X			X				X	X	X	X										
Windows Server 2003 x64 Edition	X		X	X			X				X	X	X	X										
Windows Server 2008	X		X	X			X				X	X	X	X										
Windows Server 2008 x64 Edition	X		X	X			X				X	X	X	X										
Mac OS X	X	X	X			X	X				X	X	X	X	X			X		X	X	X		X
Linux																		X						