

	Drucken	TWAIN/WIA	ICA	Duplex Drucken	Broschürendruck	SANE	Scan-to-E-Mail/Bild/Text/Datei	Scan-to-USB-Stick	Scan-to-Speicherkarte	Speicherkarten-Station	USB-Host	PC-Fax Senden	PC-Fax Empfangen	PaperPort	Presto! Page Manager	Control Center	Remote Setup	Brother Status Monitor	Web-based Management	BRAdmin Light
Windows 8	x	x		x	x		x					x	x	x		x	x	x	x	x
Windows 8 x64	x	x		x	x		x					x	x	x		x	x	x	x	x
Windows 2000	x	x		x	x		x	x	x	x	x	x	x	x		x	x	x	x	x
Windows XP	x	x		x	x		x	x	x	x	x	x	x	x		x	x	x	x	x
Windows XP x64 Edition	x	x		x	x		x	x	x	x	x	x	x	x		x	x	x	x	x
Windows Vista	x	x		x	x		x	x	x	x	x	x	x	x		x	x	x	x	x
Windows Vista x64 Edition	x	x		x	x		x	x	x	x	x	x	x	x		x	x	x	x	x
Windows 7	x	x		x	x		x	x	x	x	x	x	x	x		x	x	x	x	x
Windows 7 x64 Edition	x	x		x	x		x	x	x	x	x	x	x	x		x	x	x	x	x
Windows Server 2003	x			x	x			x	x	x	x									
Windows Server 2003 x64 Edition	x			x	x			x	x	x	x									
Windows Server 2008	x			x	x			x	x	x	x									
Windows Server 2008 x64 Edition	x			x	x			x	x	x	x									
Mac OS X	x		x	x	x		x	x	x	x	x	x	x	x					x	
Linux	x		x	x	x	x					x				x					